

Applicable Models:

DHI-HCVR5232AN-S3,DHI-HCVR7116H-S3,DHI-HCVR7116HE-S3,DHI-HCVR7216A-S3,DHI-HCVR7216AN-S3

New features:

1. Access to the OSD prompt
2. New fan and cabinet temperature data display function
3. Support more simulation front end
4. Optimize coaxial control protocol
5. Optimize the access ability of digital channels
6. Add the mandatory password and add the encryption protection function, that is to enter the mandatory change password interface after the boot selection language

Optimizations & bug fixes:

1. NTP failed to reconnect
2. Noise reduction of the 5X32 rating system
3. In TVI1.0, the problem is not recognized

Upgrade Guidance:

[Main Firmware]Update Main firmware to enjoy new features and multi-language. Including English, Polish, Greek, Serbian, Finnish, Romanian, Czech, Bulgarian, Hungarian, Slovenian, Danish and Swedish.