

**Applicable Models:**

DHI-HCVR5424L-S2;DHI-HCVR5424L;DHI-HCVR5432L-S2;DHI-HCVR5432L;DHI-HCVR5824S-S2;DHI-HCVR5824S;DHI-HCVR5832S-S2;DHI-HCVR5832S;DHI-HCVR7404L(V2.0);DHI-HCVR7408L(V2.0);DHI-HCVR7416L;DHI-HCVR7804S(v2.0);DHI-HCVR7808S(v2.0);DHI-HCVR7816S

**New features:**

1. Add the mandatory password and add the encryption protection function, that is to enter the mandatory change password interface after the boot selection language

**Optimizations & bug fixes:**

1. The Opensource library removes the RC4 algorithm
2. Fixing the name of the phone to modify the channel cannot refresh the problem
3. Fix video for error reporting

**Upgrade Guidance:**

[Main Firmware]Update Main firmware to enjoy new features and multi-language. Including English, Polish, Greek, Serbian, Finnish, Romanian, Czech, Bulgarian, Hungarian, Slovenian, Danish and Swedish.